

AURA WATERBORNE EXTERIOR PAINT SATIN FINISH 631

Features

- Extreme hide, never more than two coats in any color
- Color lock technology and extreme UV resistance
- Low temperature application
- Superior adhesion
- Delivers a high-build paint film for excellent durability
- Soap and water clean up
- · Fast dry and re-coat times
- Resistant to fading, cracking, peeling, chalking blistering, dirt pick-up
- Provides a mildew resistant film
- Self priming in most situations
- Vapor permeable

General Description

A super premium quality, 100% acrylic exterior satin latex finish. This product combines the advantages of our latest resin technology and our proprietary Gennex® colorant system to provide the ultimate exterior coating. This high solids formula is suitable for a variety of exterior surfaces and can be applied as low as 40°F.

Recommended For

Recommended for exterior use on wood, fiber cement board, hard board, vinyl and aluminum siding, shakes, unglazed brick, concrete, stucco, cinder block and primed metal.

Limitations

 Do not apply when air and surface temperatures are below 40°F (4.4°C).

Colors:—Standard:	Technical Data	Pastel Base	
White (01)	Vehicle Type	100% Acrylic Latex	
—Tint Bases:	Pigment Type	Titanium Dioxide	
1X, 2X, 3X, & 4X Tint Bases only with Gennex® Waterborne Colorant	Volume Solids	40.4%	
—Special Colors:	Coverage per Gallon at Recommended Film Thickness	250 – 350 Sq. Ft.	
Contact your Benjamin Moore representative	Recommended Film - Wet	4.6 – 6.4 mils	
Certification:	Thickness – Dry	1.9 – 2.6 mils	
VOC compliant in all regulated areas	Depending on surface texture and porosity. Be sure to estimate the right amount of paint for the job. This will ensure cold uniformity and minimize the disposal of excess paint.		
The following results are based on independent, third-party laboratory testing:	Dry Time @ 77° F — To Touc (25° C) @ 50% RH — To Reco		
-Passes Wind Driven Rain Test (1.3 oz) ASTM D6904 (TT-C-555B) 1 coat 066 Moore's Masonry Sealer @ 4 mils WFT 1 coats Aura Exterior Paint Satin Finish 631 each @ 1.85 DFT	Painted surfaces can be washed after two weeks. High humidity and cool temperatures will result in longer dry, recoat and service times.		
-Passes Alkali Resistance Test (24 hrs. no effect)	Dries By E	vaporation, Coalescence	
ASTM D1308 1 coat 066 Moore's [®] Masonry Sealer @ 4 mils WFT	Viscosity	102 ± 2 KU	
1 coats Aura® Exterior Paint Satin Finish 631 each @ 1.85 DFT	Flash Point	None	
-Passes Conical Mandrel Flexibility Test (no cracking)	Gloss / Sheen	Satin (25-35 @ 60°)	
ASTM D522 1 coat Aura [®] Exterior Paint Satin Finish 631 @ 1.6 DFT	Surface Temperature - Min.	40° F	
-Passes Mildew, Mold Resistance Test (no growth)	at Application – Max	90° F	
ASTM D3273	Thin With	See Chart	
-ASTM D1653 Water Vapor Transmission Properties 60.2 perms @ 2.0 mils DFT	Clean Up Thinner	Clean Water	
-ASTM D2370	Weight Per Gallon	11.2 lbs	
Tensile Properties Peak Tensile Strength, psi 406	Storage Temperature – Min.	40° F	
Elongation at Break, percent 380	– Max	90° F	
Technical Assistance:		Volatile Organic Compounds (VOC)	
Available through your local authorized independent Benjamin Moore® retailer. For the location of the retailer nearest you, call 1-800-826-2623, se www.benjaminmoore.com, or consult your local Yellow Pages.	44 Grams / Liter 0.37 LBS / Gallon		

 $\Diamond \mbox{Reported}$ values are for Pastel Base. Contact Benjamin Moore for values of other bases or colors.

Surface Preparation

Surfaces must be clean and free of grease, wax, and mildew. Remove any chalk and loose or scaling paint. If previously coated with cementbase waterproofing paints, clean by sandblasting. Glossy surfaces must be dulled. Un-weathered areas such as eaves, ceilings, and overhangs should be washed with a detergent solution and/or rinsed with a strong stream of water from a garden hose to remove contaminants that can interfere with proper adhesion. Stains from mildew must be removed by cleaning with Benjamin Moore® Clean (318) prior to coating the surface. Caution: Refer to the (318) Clean technical data and material safety data sheets for instructions on its proper use and handling. For metal surfaces, remove rust. Wipe down with paint thinner to remove surface

Difficult Substrates: Benjamin Moore offers a number of specialty primers for use over difficult substrates such as bleeding woods, grease stains, crayon markings, hard glossy surfaces, or other substrates where paint adhesion or stain suppression is a particular problem. Your Benjamin Moore® retailer can recommend the right problem-solving primer for your special needs.

WARNING! If you scrape, sand or remove old paint, you may release lead dust. LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH-approved respirator to control lead exposure. Carefully clean up with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the National Lead Information Hotline at 1-800-424-LEAD or log on to www.epa.gov/lead.

Primer/Finish Systems

Aura® Waterborne Exterior Satin Finish is self priming on most properly prepared substrates, including: wood, fiber cement board, hardboard, nonferrous metals and cured masonry surfaces. On bare substrates two coats are required; previously painted surfaces can be finished with 1 or 2 coats. Special Note: For certain deep colors, Aura® Color Foundation must be used to achieve maximum hide and the desired topcoat color. Consult your retailer.

Wood and engineered wood products:

Primer: No primer needed Finish: 2 coats Aura® Waterborne Exterior Paint Flat Finish (629)

Bleeding Type Woods, (Redwood and Cedar):

Primer: Fresh Start[®] Fast Dry Alkyd Primer (094); for light tannin bleed situations 1 or 2 coats of Fresh Start[®] 100% Acrylic Superior Primer (046) may be used

Finish: 1 or 2 coats Aura® Waterborne Exterior Paint Satin Finish (631)

Hardboard Siding, Bare or Factory Primed:

Primer: Fresh Start® Fast Dry Alkyd Primer (094), Fresh Start® all Purpose 100% Acrylic Primer (N023) or Fresh Start® 100% Acrylic Superior Primer (046)

Finish: 1 or 2 coats Aura® Waterborne Exterior Paint Satin Finish (631) Vinyl & Vinyl Composite Siding

Note: Ensure that the surface is properly cleaned and in good condition. For colors that are safe for use on these substrates, use approved Vinyl Select colors. For more information, see

http://www.benjaminmoore.com/en-us/for-contractors/painting-vinyl-andaluminum-siding

Primer: Fresh Start® Multi-Purpose Latex Primer (N023).
Finish: 1 or 2 coats Aura® Waterborne Exterior Paint Satin Finish (631) Rough or Pitted Masonry: Poured and precast concrete and block construction should be allowed to cure for at least 30 days. New masonry only needs to be cured for 7 days when using Super Spec® Masonry Interior / Exterior 100% Acrylic Masonry Sealer (N/066). All surfaces must be thoroughly brushed with stiff fiber bristles to remove loose particles

Primer: Super Spec[®] Latex Block Filler (160) or Super Spec[®] Masonry Interior/Exterior Hi-Build Block Filler (206)

Finish: 1 or 2 coats Aura® Waterborne Exterior Paint Satin Finish (631)

Poured or Pre-cast Concrete and Fiber Cement Siding:

Primer: No primer needed

Finish: 1 or 2 coats Aura® Waterborne Exterior Paint Satin Finish (631) Masonry, Weathered and Unpainted, Soft with Age (Including Unglazed Brick): Remove any loose, sandy masonry by dry brushing.

Primer: Super Spec® Masonry Interior / Exterior 100% Acrylic Masonry Sealer (N/066) or Super Spec® Alkyd Masonry Sealer (C077)

Finish: 1 or 2 coats Aura® Waterborne Exterior Paint Satin Finish (631) Ferrous Metal (Steel and Iron):

Primer: Super Spec HP[®] Acrylic Metal Primer (P04) or Super Spec HP[®] Alkyl Metal Primer (P06)

Finish: 1 or 2 coats Aura® Waterborne Exterior Paint Satin Finish (631)

Non-Ferrous Metal (Galvanized & Aluminum): All new metal surfaces must be thoroughly cleaned with Super Spec HP® Oil & Grease Emulsifier (P83) to remove contaminants. New shiny non-ferrous metal

metal surfaces that will be subject to abrasion should be dulled with very fine sandpaper or a synthetic steel wool pad to promote adhesion

Primer: Not required on properly prepared surfaces

Finish: 1 or 2 coats Aura® Waterborne Exterior Paint Satin Finish (631)

Repaint, All Substrates: Prime bare areas with the primer recommended for the substrate above.

Application

Use the same application techniques as you would for any low-VOC compliant coating. Use a Benjamin Moore Premium roller or Premium extra firm nylon polyester brush for best results. Aura paint features excellent flow and leveling; it's not necessary to over brush to smooth out brush marks. Aura dries faster than other acrylic paints; avoid lap marks by not painting in direct sunlight and by coating sections of the surface either down or across the structure to natural breaks, maintaining a wet edge. If your edge begins to dry or you see that you missed a spot and the paint is already setting up, allow it to dry completely before touching up that area. This product can also be sprayed.

Thinning/Cleanup

Conditioning with Benjamin Moore® 518 Extender may be necessary under certain conditions to adjust open time or spray characteristics.

The chart below is for general guidance			
	Mild conditions	Severe conditions	
	Humid (RH> 50%) with no direct sunlight & with little to no wind	Dry (RH<50%), in direct sunlight, or windy conditions	
Brush : Nylon / Polyester		Add 518 Extender or water:	
Roller : Aura [®] Roller Cover	No thinning necessary	Max of 8 fl. oz. to a gallon paint	
Spray: Airless Pressure: 2000 -3000 psi Tip: 0.015-0.017		Never add other paints or solvents.	

' Under normal application conditions AURA® may be sprayed to achieve a high build one coat system over properly prepared substrates that are in good condition. Refer to Surface Preparation / Priming Sections for appropriate priming and preparation information.

High Build System Coverage: 160 – 265 sq. ft. 6-10 mils wet film

Cleanup: Wash painting tools in warm soapy water immediately after use. Spray equipment should be given a final rinse with mineral spirits to prevent

USE COMPLETELY OR DISPOSE OF PROPERLY. Dry, empty containers may be recycled in a can recycling program. Local disposal requirements vary; consult your sanitation department or state-designated environmental agency on disposal options.

Environmental, Health & Safety Information

Use only with adequate ventilation. Do not breathe spray mist or sanding dust. Ensure fresh air entry during application and drying. Avoid contact with eyes and prolonged or repeated contact with skin. Avoid exposure to dust and spray mist by wearing a NIOSH approved respirator during application, sanding and clean up. Follow respirator manufacturer's directions for respirator use. Close container after each use. Wash thoroughly after

WARNING: This product contains a chemical known to the state of California to cause cancer and birth defects, or other reproductive

FIRST AID: In case of eye contact, flush immediately with plenty of water for at least 15 minutes; for skin, wash thoroughly with soap and water. If symptoms persist, seek medical attention. If you experience difficulty breathing, leave the area to obtain fresh air. If continued difficulty is experienced, get medical attention immediately.

IN CASE OF SPILL - Absorb with inert material and dispose of as specified under Thinning/Cleanup.

KEEP OUT OF REACH OF CHILDREN PROTECT FROM FREEZING Refer to Material Safety Data Sheet for additional health and safety information.

Benjamin Moore & Co., 101 Paragon Drive, Montvale, NJ 07645 Tel: (201) 573-9600 Fax: (201) 573-9046 www.benjaminmoore.com M72 631 US 080912

Aura, Benjamin Moore, Fresh Start, Gennex, Super Spec, Super Spec HP and the triangle "M" symbol

are registered trademarks of Benjamin Moore & Co.. © 2009, 2012 Benjamin Moore & Co. All rights reserved